=> d his full

(FILE 'HOME' ENTERED AT 15:11:04 ON 09 JUN 2006)

FILE 'CAPLUS' ENTERED AT 15:11:23 ON 09 JUN 2006 L1 0 SEA ABB=ON PLU=ON US20020050629/PN

FILE 'WPIX' ENTERED AT 15:13:10 ON 09 JUN 2006 1 SEA ABB=ON PLU=ON US20020050629/PN L2D IFULL

L3 1142410 SEA ABB=ON PLU=ON SEMICONDUCT? OR WAFER OR IC OR SEMI(W) CONDU CT? OR CHIP OR MICRO(W) CHIP OR MICROCHIP OR INTEGRATED (W) CIRCUI T OR TRANSISTOR

299675 SEA ABB=ON PLU=ON INTERCONNECT OR DAMASCE? OR LSI OR ULSI OR L4VLSI OR IC OR LARGE SCALE INTEGRAT?

172033 SEA ABB=ON PLU=ON INSULAT?(3W)(?LAYER OR ?FILM OR ?COAT? OR L5 LAMINAT? OR DEPOSI?)

L6 166996 SEA ABB=ON PLU=ON (ADHESI? OR ADHER? OR STICK? OR CLING? OR BOND?)(4W)(?LAYER OR ?FILM OR ?COAT? OR LAMINAT? OR DEPOSI?)

L7 45874 SEA ABB=ON PLU=ON PASSIV?

L8 159418 SEA ABB=ON PLU=ON PECVD OR CVD OR PLASMA OR LPCVD OR HFCVD OR PACVD OR PCVD OR (CHEMICAL? OR CHEM. OR PRECURSOR? OR ORGANIC) (4W) (VAPOR? OR VAPOUR? OR PLASMA) (4W) (DEP? OR DEPOSIT? OR COAT? OR EPITAX?)

L9 39140 SEA ABB=ON PLU=ON (SI3N4 OR SILICON NITRIDE OR SI(W) NITRIDE)

L10 91505 SEA ABB=ON PLU=ON SILICON DIOXIDE OR SIO2 OR SIO

4112 SEA ABB=ON PLU=ON SILICON OXYNITRIDE OR SION OR SI OXYNITRIDE L11

L12 78652 SEA ABB=ON PLU=ON POLYIMIDE OR ?IMIDE?

L13 1 SEA ABB=ON PLU=ON L3 AND L4 AND L5 AND L6 AND L7 AND L8 AND L9 AND L10 AND L11 AND L12

L14 1 SEA ABB=ON PLU=ON L13 NOT L2 D IFULL

L15 1 SEA ABB=ON PLU=ON L3 AND L4 AND L5 AND L6 AND L7 AND L9 AND L10 AND L11 AND L12

L16 0 SEA ABB=ON PLU=ON L15 NOT L14

L17 1 SEA ABB=ON PLU=ON L4 AND L5 AND L6 AND L7 AND L8 AND L9 AND L10 AND L11 AND L12

L18 O SEA ABB=ON PLU=ON L17 NOT L15

13 SEA ABB=ON PLU=ON L4 AND L5 AND L6 AND L7 AND L8 L19

11 SEA ABB=ON PLU=ON L19 NOT (L2 OR L13) D IALL 1-11

L20

L25

L21 2291 SEA ABB=ON PLU=ON L7 (4W) (FIRST OR SECOND OR DOUBLE OR DUPLICAT? OR MULTIP? OR SEVERAL OR TWO OR DUAL OR BOTH)

L22 1 SEA ABB=ON PLU=ON L5 AND L6 AND L8 AND L9 AND L10 AND L11 AND L12 AND L21

L23 4 SEA ABB=ON PLU=ON L5 AND L6 AND L8 AND L9 AND L12 AND L21 L24

2 SEA ABB=ON PLU=ON L23 NOT (L2 OR L13 OR L20)

D IFULL 1-2

10 SEA ABB=ON PLU=ON L21 AND L5 AND L6 AND L12

5 SEA ABB=ON PLU=ON L25 NOT (L2 OR L13 OR L20 OR L24) L26 D IFULL 1-5

FILE 'CAPLUS' ENTERED AT 15:59:01 ON 09 JUN 2006 805789 SEA ABB=ON PLU=ON SEMICONDUCT? OR WAFER OR IC OR SEMI(W) CONDU L27

```
CT? OR CHIP OR MICRO(W) CHIP OR MICROCHIP OR INTEGRATED (W) CIRCUI
                T OR TRANSISTOR
          64285 SEA ABB=ON PLU=ON INTERCONNECT OR DAMASCE? OR LSI OR ULSI OR
L28
                VLSI OR IC OR LARGE SCALE INTEGRAT?
        97847 SEA ABB=ON PLU=ON INSULAT? (3W) ( ?LAYER OR ?FILM OR ?COAT? OR
                LAMINAT? OR DEPOSI?)
L30
        121510 SEA ABB=ON PLU=ON (ADHESI? OR ADHER? OR STICK? OR CLING? OR
                BOND?) (4W) ( ?LAYER OR ?FILM OR ?COAT? OR LAMINAT? OR DEPOSI?)
L31
          1849 SEA ABB=ON PLU=ON L7 (4W) (FIRST OR SECOND OR DOUBLE OR
                DUPLICAT? OR MULTIP? OR SEVERAL OR TWO OR DUAL OR BOTH)
L32 930106 SEA ABB=ON PLU=ON PECVD OR CVD OR PLASMA OR LPCVD OR HFCVD
                OR PACVD OR PCVD OR (CHEMICAL? OR CHEM. OR PRECURSOR? OR
                ORGANIC) (4W) (VAPOR? OR VAPOUR? OR PLASMA) (4W) (DEP? OR DEPOSIT?
                OR COAT? OR EPITAX?)
    FILE 'REGISTRY' ENTERED AT 16:01:47 ON 09 JUN 2006
            1 SEA ABB=ON PLU=ON SILICON NITRIDE/CN
1 SEA ABB=ON PLU=ON SILICON DIOXIDE/CN
2 SEA ABB=ON PLU=ON SILICON OXYNITRIDE/CN
L33
L34
L35
L36
         55103 SEA ABB=ON PLU=ON POLYIMIDE/PCT
    FILE 'CAPLUS' ENTERED AT 16:02:55 ON 09 JUN 2006
      78069 SEA ABB=ON PLU=ON L33
L37
L38
        353471 SEA ABB=ON PLU=ON L34
L39
         9330 SEA ABB=ON PLU=ON L35
L40
         36825 SEA ABB=ON PLU=ON L36
L41
        93391 SEA ABB=ON PLU=ON L37 OR L9
      568544 SEA ABB=ON PLU=ON L38 OR L10
L42
L43
        10942 SEA ABB=ON PLU=ON L11 OR L39
       235844 SEA ABB=ON PLU=ON L12 OR L40
L44
L45
             11 SEA ABB=ON PLU=ON L37 AND L38 AND L39 AND L40 AND L41 AND
               L42 AND L43 AND L44
               D IBIB ABS HITSTR HITIND 1-11
     FILE 'INSPEC' ENTERED AT 16:13:42 ON 09 JUN 2006
    FILE 'INSPEC, COMPENDEX' ENTERED AT 16:13:51 ON 09 JUN 2006
L46
      1599970 SEA ABB=ON PLU=ON L3
        245340 SEA ABB=ON PLU=ON L4
L47
L48
        13650 SEA ABB=ON PLU=ON L5
        29596 SEA ABB=ON PLU=ON L6
L49
L50
         5413 SEA ABB=ON PLU=ON L21
L51
        540027 SEA ABB=ON PLU=ON L8
L52
        38729 SEA ABB=ON PLU=ON L9
L53
       153015 SEA ABB=ON PLU=ON L10
L54
         3920 SEA ABB=ON PLU=ON L11
L55
        34807 SEA ABB=ON PLU=ON L12
L56
             O SEA ABB=ON PLU=ON L46 AND L47 AND L48 AND L49 AND L50 AND
             0 SEA ABB=ON PLU=ON L48 AND L49 AND L50 AND L51
L57
```

0 SEA ABB=ON PLU=ON L47 AND L48 AND L49 AND L50 AND L51

L58